BOARD OF WATER SUPPLY

CITY AND COUNTY OF HONOLULU 630 SOUTH BERETANIA STREET HONOLULU, HI 96843



KIRK CALDWELL, MAYOR

DUANE R. MIYASHIRO, Chair ADAM C. WONG, Vice Chair DAVID C. HULIHEE KAPUA SPROAT BRYAN P. ANDAYA

ROSS S. SASAMURA, Ex-Officio FORD N. FUCHIGAMI, Ex-Officio

ERNEST Y. W. LAU, P.E. Manager and Chief Engineer

ELLEN E. KITAMURA, P.E.
Deputy Manager and Chief Engineer

Dr. Virginia Pressler Director State of Hawaii Department of Health P.O. Box 3378 Honolulu, Hawaii 96801

Dear Dr. Pressler:

Subject: Navy Groundwater Monitor Well Test Results - Second Quarter 2015

The subject test results show the second quarter total petroleum hydrocarbon (TPH) diesel levels are higher than the first quarter 2015 results for most of the monitor wells tested. The highest increase is at Red Hill monitor well 02 where the second quarter result is 5,200 parts per billion (ppb) compared to 1,100 ppb in the first quarter. Does the Department of Health know the reason for the increase? We would appreciate your comments on the results.

Thank you for your assistance in this matter. If you have any questions, please feel free to call me at 748-5061.

Very truly yours,

ERNEST Y. W. LAU, P.E. Manager and Chief Engineer