

## **DEPARTMENT OF THE NAVY**

COMMANDER NAVY REGION HAWAII 850 TICONDEROGA ST STE 110 JBPHH, HAWAII 96860-5101





5090 Ser N45/1076 October 01, 2013

*ω*-

## CERTIFIED MAIL NO. 7011 2000 0002 7214 2896

Mr. Richard Takaba Hawaii State Department of Health Environmental Management Division Solid and Hazardous Waste Branch Underground Storage Tank Section 919 Ala Moana Boulevard, Room 212 Honolulu, HI 96814

Dear Mr. Takaba:

SUBJECT: RED HILL TANK COMPLEX, JULY 2013 GROUNDWATER

MONITORING RESULTS FOR OUTSIDE (NON-TUNNEL) WELLS, FACILITY ID NO. 9-102271, RELEASE ID NO. 99051, 010011, AND 020028

On July 24, 2013, Environmental Science International, Inc. (ESI) collected groundwater samples from wells HDMW2253-03 and OWDFMW01, which are located outside the Red Hill Fuel Storage Facility. The Navy is submitting the Third Quarter 2013 - Quarterly Groundwater Monitoring Report for Outside Tunnel Wells as Enclosure 1.

The groundwater samples were analyzed for petroleum constituents. Laboratory analytical results indicate all chemical of potential concern (COPC) concentrations were below the DOH Drinking Water Toxicity EALs and the DOH Groundwater Gross Contamination EALs, except for TPH-D. TPH-D was detected at concentrations of 470 and 340 ug/L in OWDFMW01, which were above the DOH EAL for Gross Contamination (100 ug/L) and the DOH EAL for Drinking Water Toxicity (190 ug/L).

The TPH-d results for the primary and duplicate samples collected from groundwater monitoring well OWDFMW01 were flagged with a laboratory data qualifier since the groundwater samples exhibited a chromatographic pattern that did not resemble the reference fuel standard. The concentrations quantified as TPH-d may not be representative of diesel fuel contamination at the site.

Continued quarterly sampling is recommended for both groundwater monitoring wells. The next sampling event is scheduled for October 2013. A groundwater monitoring report for

5090 Ser N45/1076 October 01, 2013

the October 2013 sampling event will be prepared and submitted to the DOH.

If there are any questions regarding this matter, or if more information is needed, please contact Ms. Raelynn Kishaba at (808) 471-1171, extension 233.

Sincerely

AARON Y POENTIS

Director

Regional Environmental Department By direction of the Commander

Enclosures: 1.

- 1. Third Quarter 2013 Quarterly Groundwater Monitoring Report, Outside Tunnel Wells, Red Hill Bulk Fuel Storage Facility, Joint Base Pearl Harbor-Hickam, Oahu, Hawaii of September 2013 (1 hard copy)
- 2. Third Quarter 2013 Quarterly Groundwater Monitoring Report, Outside Tunnel Wells, Red Hill Bulk Fuel Storage Facility, Joint Base Pearl Harbor-Hickam, Oahu, Hawaii of September 2013 (1 CD)

Copy to: Ms. Joanna Seto, DOH Safe Drinking Water Branch (1 CD)
Mr. Christopher Lau, NAVSUP Fleet Logistics Center
Pearl Harbor (1 hard copy, 1 CD)