RED HILL - BIENNIAL TEST HISTORY

All test performed with the Mass Technology Corporation method

Discription			2008			2009			2011			2013		
TANK #	Diameter (ft)	Depth (ft)	Completion Date	MDLR	Results	Completion Date	MDLR	Results	Completion Date	MDLR	Results	Completion Date	MDLR	Results
1	100	250				Not in service			Removed From Service			Removed From Service		
2	100	250				6/24/2009	0.7	PASS	2/8/2012	0.7	PASS	2/20/2013	0.7	PASS
3	100	250				3/9/2009	0.7	PASS	2/21/2011	0.7	PASS	3/7/2-03	0.7	PASS
4	100	250				6/5/2009	0.7	PASS	3/17/2011	0.7	PASS	4/5/2013	0.7	PASS
5	100	250				6/18/2009 0.7 PASS			Out of Service for Inspection			Out of Service for Inspection		
6	100	250				3/15/2009	0.7	PASS	2/13/2011	0.7	PASS	3/22/2013	0.7	PASS
7	100	250				4/9/2009	0.7	PASS	1/21/2011	0.7	PASS	2/14/2013	0.7	PASS
8	100	250				5/12/2009	0.7	PASS	3/11/2011	0.7	PASS	2/13/2013	0.7	PASS
9	100	250	3/11/2008	0.5	Pass	Tested 2008			3/9/2011	0.7	PASS	2/28/2013	0.7	PASS
10	100	250				5/19/2009	0.7	PASS	1/13/2011	0.7	PASS	2/6/2013	0.7	PASS
11	100	250				6/2/2009	0.7	PASS	1/13/2011	0.7	PASS	2/7/2013	0.7	PASS
12	100	250				5/26/2009	0.7	PASS	2/6/2011	0.7	PASS	3/1/2013	0.7	PASS
13	100	250				5/19/2009	0.7	PASS	2/25/2011	0.7	PASS	3/29/2013	0.7	PASS
14	100	250				6/11/2009 0.7 PASS		3/4/2011	0.7	PASS	Out of Se	rvice for In	spection	
15	100	250	3/11/2008	0.5	Pass	Tested 2008			3/25/2011	0.7	PASS	2/22/2013	0.7	PASS
16	100	250				5/12/2009	0.7	PASS	2/28/2011	0.7	PASS	3/15/2013	0.7	PASS
17	100	250				4/8/2009 0.7 PASS			Out of Service for Inspection			Out of Service for Inspection		
18	100	250				5/29/2009	0.7	PASS	1/28/2011	0.7	PASS	1/30/2013	0.7	PASS
19	100	250				Not in service			Removed From Service			Removed From Service		
20	100	250				Not in service			3/18/2011	0.7	PASS	1/31/2013	0.7	PASS